

SEELY OIL COMPANY

815 WEST TENTH STREET
FORT WORTH, TEXAS 76102

August 3, 2001

State of New Mexico
Energy, Mineral and Natural Resources Dept.
Oil Conservation Division
1625 North French Drive
Hobbs, New Mexico 88240

Attention: Mr. Gary Wink

Re: Repair of Water Injection Well
EK Queen Unit #67
EK Yates – SR – Queen Field
API No: 30-025-02350

Dear Mr. Wink:

Seely Oil Company forwarded a C-103 Sundry Notice for OCD approval to repair the subject water injection well. A copy of the C-103 is enclosed. The work has yet to be performed.

A recent mechanical integrity test was performed which showed a leak in the wellbore.

This letter serves as notice that we plan to proceed with the repair work as soon as a workover unit can be obtained.

If any additional information is required, please do not hesitate to contact me.

Very truly yours,

SEELY OIL COMPANY



David L. Henderson

DLH:pa

Enclosure