

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type or Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	E-3072-3

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Injection Well</u>	7. Unit Agreement Name <u>East E.K.</u>
2. Name of Operator <u>Continental Oil Company</u>	8. Farm or Lease Name <u>East E.K. Unit</u>
3. Address of Operator <u>P.O. Box 460 Hobbs, N.M. 88240</u>	9. Well No. <u>6</u>
4. Location of Well UNIT LETTER <u>P</u> <u>460</u> FEET FROM THE <u>South</u> LINE AND <u>460</u> FEET FROM THE <u>East</u> LINE, SECTION <u>22</u> TOWNSHIP <u>12S</u> RANGE <u>34E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>E.K. Queen</u>
11. Elevation (Show whether DF, RT, GR, etc.) <u>4015' GR</u>	12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well was cleaned out and acidized as follows:

9-26. Mixed, pull inj. eqpt., run wk. string.
Rumped 18 bbls Para-Clean acid & 36 bbls
flush.

9-27 Pull work string, run inj. eqpt., place well on inj.
10-1 200 bbl rate @ 2600 ps.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Wm. R. Butterfield</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>10-5-78</u>
APPROVED BY <u>Jerry Hester</u>	TITLE <u>DATE 10-5-78</u>	DATE <u>OCT 10 1978</u>