

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-025-03039
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name George McGonagill
2. Name of Operator Saga Petroleum LLC	8. Well No. 1
3. Address of Operator 415 W. Wall, Suite 1900 Midland, TX 79701	9. Pool name or Wildcat Vac Grayburg San Andres
4. Well Location Unit Letter A : 330 feet from the NORTH line and 990 feet from the EAST line Section 2 Township 18S Range 35E NMPM County LEA	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3891Gr 3904' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐

OTHER:

CONDITIONS OF APPROVAL

12. Describe proposed or completed operations. (Clearly of starting and proposed work). SEE RULE 1103. For recompletion.
17" hole, 13-3/8" 48# csg @ 320' w/330 sx - circ
11" hole, 8-5/8" 24 & 32# csg @ 3498' w/1365 sx - circ
7-7/8" hole, 5-1/2" 15.5 & 17# csg @ 9259' w/720 sx - TOC 3500' by TS
CIBP @ 4970' w/2sx cmt & CIBP @ 8600' w/2 sx cmt. Open perms 4790'-4846' & 8780'-8808'. Wellbore diagram attached
Set 5-1/2" CIBP @ 4750' - dump 35' cmt on top.
Spot 100' plug from 3548'-3448' (50' in & 50' out), tag
Spot 100' plug from 370'-270' (50' in & 50' out), tag
25 sx plug 50' @ surface w/dry hole marker
→ SPOT 100' PLUG F/1830' to 1930' (T.O.S.)

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 02/12/2002

Type or print name Bonnie Husband Telephone No. (915)684-4293

(This space for State use)

APPROVED BY _____ DATE FEB 21 2002

Conditions of approval, if any:

Handwritten signature