Submit 3 Copies To Appropriate District Office	State of New Energy Minerals and N			Form C-103
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals and Natural Resources		Reweich WELL API NO.	evised March 25, 199
District II	OIL CONSERVATION DIVISION		30-025-03048	
811 South First, Artesia, NM 87210 District III	2040 South Pacheco		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE <b>X</b> I	FEE
<u>District IV</u> 2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & Gas Lease	No.
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPLIC	CES AND REPORTS ON W OSALS TO DRILL OR TO DEEPE CATION FOR PERMIT" (FORM C	N OR PLUG BACK TO A	<b>B-1231</b> 7. Lease Name or Unit Ag	greement Name:
PROPOSALS.)			Vacuum ABO Unit	
1. Type of Well: Oil Well 🕱 Gas Well 🗌	Other		Tract 13	
2. Name of Operator			8. Well No.	
Phillips Petroleum Company			08	
3. Address of Operator			9. Pool name or Wildcat	
4001 Penbrook Street Odessa, 4. Well Location	TX 79762	·	Vacuum ABO Reef	
Unit Letter D:	330 feet from the	North line and	990 feet from the	West line
Section 4	Township <b>18-S</b>		NMPM Cour	nty <b>Lea</b>
	10. Elevation (Show wheth		c.)	
11 Check /		GR / 3961 'RKB	Depart of Other Def	
	Appropriate Box to Indica			05
			SEQUENT REPORT	-
		_		ERING CASING
EMPORARILY ABANDON	CHANGE PLANS			G AND NDONMENT
PULL OR ALTER CASING	MULTIPLE C	CASING TEST AND CEMENT JOB		
DTHER:				
<ol> <li>Describe Proposed or Complete of starting any proposed work). or recompilation.</li> </ol>	J Operations (Clearly state al SEE RULE 1103. For Multip	All pits must be lined All shoe plugs, stub p be tagged	lugs & cement plugs above	·
				100 0
Plug and abandon proceeding	before and often and 11			minimum 100 feet
Plug and abandon procedure		bore schematics atta	iched.	minimum 100 feet
Plug and abandon procedure	ente productiva de la companya de la Companya de la companya de la company	bore schematics atta	ched.	minimum 100 feet
Plug and abandon procedure		bore schematics atta	ched.	minimum 100 feet
Plug and abandon procedure	anto da Artegra Regensiones Regensiones Regensiones References	bore schematics atta	ched.	minimum 100 feet
	is true and complete to the best of	bore schematics atta	ched.	minimum 100 feet 02/06/02
GNATURE	is true and complete to the best of	bore schematics atta	./ProDATE_	
GNATURE	is true and complete to the best of	bore schematics atta		02/06/02 915/368-1488
ereby certify that the information above	is true and complete to the best of	bore schematics atta of my knowledge and belief TLE Supervisor, Reg.	./ProDATE NED BY Telephone No VET?	02/06/02