•		Fan C 100
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	Commission	Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		• [₹]
OPERATOR		5. State Oil & Gas Lease No.
	<del></del>	B-1503
	SUNDRY NOTICES AND REPORTS ON WELLS	X1111111111111111111111111111111111111
	FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
1.	TONN CHICIPPON SOCH PROPOSALS.)	
OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		
Phillips	Petroleum Company	8. Farm or Lease Name
3. Address of Operator	1 o d o d o d d d d d d d d d d d d d d	Santa Fe (Btry 2)
Room 806	, Phillips Bldg., Odessa, Texas 79761	9. Well No.
4. Location of Well	, inititips bidg., Odessa, lexas /9/01	3
Tr.	1090	10. Field and Pool, or Wildcat
UNIT LETTER	1980 FEET FROM THE north LINE AND 660 FEET FROM	Vacuum Gb/San Andres
		All Hill Williams
THE WEST LINE	section 5 township 18-S RANGE 35-E NMPM.	
mmmmm		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3979' RKB	Lea ()
CI	heck Appropriate Box To Indicate Nature of Notice, Report or Oth	On Date
NOTICE		REPORT OF:
	JOBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	and the second second
<b>=</b>		ALTERING CASING
TEMPORARILY ABANDON		<u> </u>
PULL OR ALTER CASING	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
PULL OR ALTER CASING		PLUG AND ABANDONMENT
PULL OR ALTER CASING OTHER	CHANGE PLANS CASING TEST AND CEMENT JQB	[
PULL OR ALTER CASING OTHER	CHANGE PLANS CASING TEST AND CEMENT JQB	[
PULL OR ALTER CASING OTHER	CHANGE PLANS CASING TEST AND CEMENT JQB	[
OTHER  17. Describe Proposed or Complimork) SEE RULE 1103.	CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  eted Operations (Clearly state all pertinent details, and give pertinent dates, including the company of the compan	estimated date of starting any propos
OTHER  OT	CHANGE PLANS  CASING TEST AND CEMENT JQB  OTHER  OTHER  eted Operations (Clearly state all pertinent details, and give pertinent dates, including the company of the compan	estimated date of starting any propos
OTHER  7. Describe Proposed or Complimork) SEE RULE 1103.	eted Operations (Clearly state all pertinent details, and give pertinent dates, including and Johnson unit, fished Kobe pump and standing valy	estimated date of starting any propos re. BJ treated down
OTHER  7. Describe Proposed or Complimork) SEE RULE 1103.	eted Operations (Clearly state all pertinent details, and give pertinent dates, including a RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot	estimated date of starting any proposes.  BJ treated down acid - 25% solvent.
OTHER  7. Describe Proposed or Complimork) SEE RULE 1103.	RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor	re. BJ treated down acid - 25% solvent
OTHER  7. Describe Proposed or Complimork) SEE RULE 1103.	RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum.	re. BJ treated down acid - 25% solvent
OTHER  7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:	RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
OTHER  7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:	RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:	RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:	RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge. P/24 hrs, 24 BLO, 7 BFO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Compinarial North 1-10-77:  1-11-77:  1-12-77:  1-13-77:	RU Johnson unit, fished Kobe pump and standing valve tog thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 15 BO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 25 BO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 27 BO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 27 BO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 27 BO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:  1-16-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 26 BO, no water, GOR 478/1, w/Kobe pump; restored to production.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,  pp. Released unit.
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:  1-16-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.	re. BJ treated down acid - 25% solvent Thushed w/25 BO, Swbd 6 hrs,  The Released unit.  Sep. Released unit.
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:  1-16-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 26 BO, no water, GOR 478/1, w/Kobe pump; restored to production.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,  pp. Released unit.
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:  1-16-77:	RU Johnson unit, fished Kobe pump and standing valve together open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/25 BO, no water.  P/26 hrs, 27 BO, no water.  P/27 hrs, 28 BO, no water.  P/28 hrs, 29 BO, no water.  P/29 hrs, 29 BO, no water, GOR 478/1, w/Kobe pump; restored to production.	re. BJ treated down acid - 25% solvent Flushed w/25 BO, Swbd 6 hrs,  pp. Released unit.
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:  1-16-77:	RU Johnson unit, fished Kobe pump and standing valve to the thru open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 26 BO, no water, GOR 478/1, w/Kobe pump; restored to production.	re. BJ treated down acid - 25% solvent Thushed w/25 BO, Swbd 6 hrs,  The Released unit.  Sep. Released unit.
PULL OR ALTER CASING  OTHER  17. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:  1-16-77:	RU Johnson unit, fished Kobe pump and standing valve together open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/25 BO, no water.  P/26 hrs, 27 BO, no water.  P/27 hrs, 28 BO, no water.  P/28 hrs, 29 BO, no water.  P/29 hrs, 29 BO, no water, GOR 478/1, w/Kobe pump; restored to production.	re. BJ treated down acid - 25% solvent. Flushed w/25 BO, Swbd 6 hrs, ap. Released unit.
7. Describe Proposed or Complework) SEE RULE 1103.  1-10-77:  1-12-77:  1-13-77:  1-14-77:  1-15-77:  1-16-77:	RU Johnson unit, fished Kobe pump and standing valve together open hole 4144-4650' w/1000 gals one shot and 75% NE HCL acid w/scale and corrosion inhibitor csg w/125 BO. Press 130# at 1 BPM. SDP on vacuum. 96 BLO, 24 BAW.  Swbd 3 hrs, 30 BLO. Loaded hole w/oil, dropped pum P/18 hrs, no gauge.  P/24 hrs, 24 BLO, 7 BFO, no water.  P/24 hrs, 25 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/24 hrs, 27 BO, no water.  P/24 hrs, 26 BO, no water.  P/25 BO, no water.  P/26 hrs, 27 BO, no water.  P/27 hrs, 28 BO, no water.  P/28 hrs, 29 BO, no water.  P/29 hrs, 29 BO, no water, GOR 478/1, w/Kobe pump; restored to production.	re. BJ treated down acid - 25% solvent. Flushed w/25 BO, Swbd 6 hrs, ap. Released unit.

CONDITIONS OF APPROVAL, IF ANY

-----

J:N 2 1877

One Comment of Comm.