

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03069
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Phillips Petroleum Company		6. State Oil & Gas Lease No. B-1713
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762		7. Lease Name or Unit Agreement Name: Vacuum ABO Unit Tract 13
4. Well Location Unit Letter G : 2080 feet from the North line and 1980 feet from the East line Section 5 Township 18-S Range 35-E NMPM County Lea		8. Well No. 07
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3952' GR / 3967' RKB		9. Pool name or Wildcat Vacuum ABO Reef

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

03/05/02 MIRU BASIC ENERGY SERVICES P & A PACKAGE #2282. OBJECTIVE: PLUG & ABANDON VACUUM ABO UNIT #13-07W. LOCATED: 2080' FNL & 1980' FEL. SEC 5, T-18-S, R-35-E, LEA COUNTY, NEW MEXICO. NOTIFIED NMOC SYLVIA DICKIE OF INTENT TO COMMENCE P & A OPERATIONS. DIG TESS #2002072005. ND WH. NU CLASS 1 BOPE. LAY DOWN PRODUCTION TUBING (2-3/8" IPC.) SECURE WELL. SDON.

03/06/02 TRAVEL TO LOCATION. FINISH LAYING DOWN PRODUCTION TBG AND PACKER. 277 JTS TBG. GIH W/WL. SET CIRP @ 8500'. POOH W/WL. PU WS. TAG CIRP @ 8500'. MIX 100 SX SALT GEL & 250 BBL BRINE WATER. (* NOTE: MLF = MUD LADEN FLUID.*) CIRC 9.5# MLF. (** NOTE: ALL PLUGS = CLASS "C" CEMENT, 14.8# DENS, 1.32 YD.**) PUMP PLUG #1 (35 SX, INTERVAL 8500 - 8146', DISPLACE W/31.5 BBL MLF.) POOH TO 6275'. PUMP PLUG #2 (25 SX, INTERVAL 6275 - 6078', DISPLACE W/23 BBL MLF.) POOH TO 4550'. PUMP PLUG #3 (80 SX, INTERVAL 4550 - 3759', DISPLACE W/14.5 BBL MLF.) POOH. SECURE WELL AND SDON.

*** CONTINUED ON BACK ***

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Stacy Sanders* TITLE Supervisor, Reg./Pro. DATE 03/22/02

Type or print name L. M. Sanders Telephone No. 915/368-1488

(This space for State use)

APPROVED BY *Johnny Robinson* TITLE COMPLIANCE OFFICER DATE JUL 0 2002
Conditions of approval, if any EW

Continued:

Vacuum ABO Unit #13-07

03/07/02 TRAVEL TO LOCATION. FINISH POOH. ND BOPE. DIG OUT CELLAR. REMOVE TBG HEAD. WELD ON 5-1/2" PULL NIPPLE. REMOVE SLIPS. FREEPOINT 5-1/2" CASING. 2865'. NU BOPE. GIH W/JET CUTTER ON WL. CUT 5-1/2" CASING @ 2865'. POOH W/WL. RIG UP CASING TOOLS. LAY DOWN 72 JTS & 2 PIECES 5-1/2" CASING. GIH W/WS TO 3300'. PUMP PLUG #4 (60 SX, INTERVAL 3300'-2815', DISPLACE W/10.7 BBL MLF.) POOH W/WS. SECURE WELL AND SDON.

03/10/02 TRAVEL TO LOCATION. GIH - TAG PLUG #4 @ 2815'. LD WS TO 1650'. PUMP PLUG #5 (25 SX, INTERVAL 1650'-1550', DISPLACE W/5 BBL MLF.) LD WS TO 375'. PUMP PLUG #6 (100 SX, INTERVAL 375'-SURFACE.) LAY DOWN WS. CLEAN OUT BOPE. ND BOPE. RDMO. PERFORM RECLAMATION WORK. CUT OFF WELLHEAD, CAP AND INSTALL DRY HOLE MARKER. P & A OPERATIONS COMPLETE. DROP WELL FROM REPORT.

MATERIAL TRANSFERS:

#799487 - 5-1/2" CASING AND TUBING
#799488 - WELLHEAD EQUIPMENT