Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 WELL API NO.

30-025-03070

5. Indicate Type of Lease

P.O. Drawer DD, Artesia, NM 88210 DISTRICT III	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	OA 7. Lease Name or Unit Agreement Name L'acuem abount Bty 2 Tr.
1. Type of Well: Off X GAS WELL X OTHER	Vac Abo
2 Name of Operator Phillips Petroleum Company	8. Well No. 23-10
3. Address of Operator HC 60 Box 66 Lovington NM 88260	9. Pool name or Wildcat Vacuum als Reef
4. Well Location Unit Letter : 1980 Feet From The FS Line and	<i>u</i> ,
Section 5 Township 18 S Range 35 E	NMPM County
10. Elevation (Show whether DF, RKB, RT, GR, etc.	
11. Check Appropriate Box to Indicate Nature of Notic	e, Report, or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	K ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRII	LLING OPNS. DPLUG AND ABANDONMENT
	ND CEMENT JOB
OTHER: OTHER:	lar inspection [
12 Pescribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103.	including estimated date of starting any proposed
1) Install risers on casing to surface	2 (2")

TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB
OTHER:				OTHER: Cellar inspection
12 Pescribe Proposed or Complework) SEE RULE 1103.	sted Open	rations (Clearly state all pertinent de	etails, an	d give pertinent dates, including estimated date of starting any proposed
	1)	Install risers on o	casir	ng to surface (2")
	2)	Banded all valves ((Sur,	Imed, or Prod)
	3)	Clean and fill cell	lars	with sand
				•
·				
	/ .*	7	<u> </u>	
I hereby certify that the information a	• ////	te and complete to the best of my knowle	_	
SIGNATURE CONTINUES	eare	ausen	mı	SR Oil & Gas Supervisor DATE /3/31/72
TYPE OR PRINT NAME				TELEPHONE NO.
(This space for State Use)	· //	//. 1		THE CAC PROPERTY OF SERVICE 1003
APPROVED BY UMA	11	Hell	m	PATE FEB 2 5 1993
CONDITIONS OF APPROVAL, IF ANY:				