

OIL CONSERVATION DIVISION

P. O. BOX 2038

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.J.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☒ ☐ Fee ☐

5. State Oil & Gas Lease No.

B-1113-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

1. Name of Operator

TEXACO Inc.

2. Address of Operator

P. O. Box 728, Hobbs, New Mexico 88240

3. Location of Well

UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM

THE West LINE, SECTION 6 TOWNSHIP 18-S RANGE 35-E N.M.P.M.

7. Unit Agreement Name

Central Vacuum Unit

8. Name of Lease Name

Central Vacuum Unit

9. Well No.

119

10. Field and Pool, or Wildcat

Vacuum Grayburg - San Andres

15. Elevation (Show whether DF, RT, GR, etc.)

3981' (GR)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install BOP.
2. Run 2 3/8" workstring to base of salt (2690').
3. Pump 400 Bbls. 10#/brine water to confirm that well is on a vacuum.
4. Pump 500 sx. Class 'C' Cement containing 2% CaCl₂ & 1/4# Flocele per sack.
5. Spot 100 sx. Class 'C' Cement plug across 5 1/2" Csg. stub @ 2260'.
6. Perforate 5 1/2" Csg w/2-JS @ 1550'. Set Cement retainer @ 1500'.
7. Squeeze w/500 sx. Class 'C' cement w/2% CaCl₂.
8. Spot 20 sx. Class 'C' Cement plug from 700' - 400'.
9. Spot 10 sx. Class 'C' Cement plug from 100' - Surface.
10. Install Dry-Hole Marker. Clean location. Well P&A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Asst. Dist. Supt.

DATE 4-15-80

APPROVED BY [Signature]

Jerry Sexton
Dist. 1. Supv.

TITLE _____

DATE APR 17 1980

CONDITIONS OF APPROVAL, IF ANY: