(This space for State Use)

APPROVED BY_

CONDITIONS OF APPROVAL, IF ANY:

DISTRICT I SUPERVISOR

TITLE

State of New Mexico

Form C-103

District Office	Ener _b ,, Minerals and	Natural R	esources Department		Rev	ised 1-1-89
DISTRICT I	OIL CONSER	VATI	ON DIVISION	WELL API NO	<u> </u>	-
P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Box 2088					3002503088	
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088				5. Indicate T	ype of Lease STATE	FEE 🗍
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 874	10			6. State Oil	Gas Lease No.	, <u>, , , , , , , , , , , , , , , , , , </u>
SUNDRY NO	TICES AND REPORTS	ON WEI	Ц.		B-1306	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Nar	ne or Unit Agreement Name	
				CENTRAL \	ACUUM UNIT	
1. Type of Well: OIL GAS WELL OTHER						
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.				8. Well No.	95	
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240				9. Pool Name		
4. Well Location				VAC	UUM GRAYBURG SAN AND	RES
Unit LetterA:	660 Feet From The	e <u>NOR</u>	TH Line and 660	Feet From ^	The <u>EAST</u> Line	
Section 6			Range 35E NM	IPM	LEA COUNT	Y
	10. Elevation (Show whet	her DF, RK	(B, RT,GR, etc.) 3973' GL			
11. Check A	ppropriate Box to Indi	cate Na	ture of Notice, Report	, or Other I	Data	
NOTICE OF INTENTION TO:				IBSEQUE	NT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	\boxtimes	ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP				RATION 🗌	PLUG AND ABANDONMEN	п 🗀
PULL OR ALTER CASING CASING TEST AND CEME			T JOB			
OTHER:		Ц_	OTHER:			🗆
12. Describe Proposed or Completed Open any proposed work) SEE RULE 110	perations (Clearly state all 3.	pertinent	details, and give pertinen	t dates, inclu	ding estimated date of st	arting
5/17/94 - 5/22/94						
1. MIRU, TOH W/ RODS & PUMP, C/O	TO 4675', SPTD 400 GALS	AMMONI	UM BICARBONATE ACRO	SS OPEN HO	DLE FR 4112'-4675'. SION	
2. SWABBED OUT AMMONIUM BICAR	BONATE. SPTD 400 GALS	20% NEI	FE ACROSS OH. SI 1 HR	& SWABBED	BACK.	
3. SET PKR @ 4000', ACIDIZED OH W	7/8000 GALS 20% NEFE. M	IAX P = 28	860#, AIR = 4.5 BPM. SI 1	HR & SWABE	BED BACK.	
4. SCALE SQZD W/ 4 DRUMS TH-793 I						
5. TAGGED FILL @ 4630', C/O TO 4665	5'. TIH W/ TBG, RODS, & P	UMP. RE	TURNED WELL TO PROD	DUCTION.		
OPT 6-16-94 PUMPING BY ROD PUM						
		00 11101 2	•			
I hereby certify that the information above is true and comple	te to the best of my knowledge and belief					
SIGNATURE North Church	TITLE	Engr /	Asst		DATE 6/28/94	
TYPE OR PRINT NAME MC	onte C. Duncan				Telephone No. 397-04	18
(This space for State Use) QNGINAL SIGNS	D BY JERRY SEXTON					

_DATE___JUL_0 5 1994

111/0 +