State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

	OIL	CONSER	VATION	DIVISION
--	-----	--------	--------	----------

P.O. Box 2088

WELL API NO.

30-025-03089

P.O. Box Drawer DD, Artesia, N	Santa Fe, New	Mexico 87504-2088	5. Indicate Type of Lease	
DISTRICT III	VIVI 66210		STATE 😿 FEE	
1000 Rio Brazos Rd., Aztec, NN	vi 87410		6. State Oil / Gas Lease No.	
(DO NOT USE THIS FORM	DRY NOTICES AND REPORTS OF FOR PROPOSALS TO DRILL OR TO INT RESERVOIR. USE "APPLICATION (FORM C-101) FOR SUCH PROPOSE.	7. Lease Name or Unit Agreement Name CENTRAL VACUUM UNIT		
1. Type of Well: OIL WELL	GAS WELL OTHER			
Name of Operator TE:	XACO EXPLORATION & PRODUCTION	ON INC.	8. Well No. 96	
	5 E. Bender, HOBBS, NM 88240		Pool Name or Wildcat VACUUM GRAYBURG SAN ANDRES	
Well Location Unit Letter B	B: 660 Feet From The	NORTH Line and 1980	Feet From The EAST Line	
Section 6	Township 18S	Range 35E		
	10. Elevation (Show whether	DF, RKB, RT,GR, etc.)		
11.	Check Appropriate Box to Indica	ate Nature of Notice, Repor	rt, or Other Data	
NOTICE OF INT			SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING O		
PULL OR ALTER CASING		CASING TEST AND CEMI	·	
OTHER:	· · ·	OTHER:	C/O & ACIDIZE	
proposed work) SEE RULE 12-07-99: MIRU. UNSEAT PU 12-08-99: TIH W/BIT, TBG. TA 12-09-99: TOH W/TBG & BAIL OF FSH @ 4661'. UNLOAD, R 12-10-99: PRESS CSG TO 50 END FL @ 3000'. 12-11-99: FL @ 2500'. END F 12-13-99: TIH W/SHOE, WP C SPOT. TAG @ 4630'. BREAK (12-14-99: LOWER TBG. TAG 12-15-99: TIH W/OPMA, PERI W/25BFW & OVER FLUSH W/ 12-16-99: TIH W/GAS ANCHO PUMPING @ 1 PM. RIG DOW	: 1103. IMP. NDWH. NUBOP. REL TAC. AG FILL @ 4675'. TIH W/BIT, BAILER LER. LEFT IN HLE: 3 1/4" BIT, BIT SU PACK, TALLY 2 3/8" WS. TIH W/PKR, 100#. ACIDIZE GBSA 4 3/4" OH 4105-40 IL @ 3500'. RD SWAB. REL PKR & TO DN TBG. TAG @ 4060'. ATTEMPT TO CIRC W/150 BW. C/O TO TOP OF FS @ 4661'. TOP OF FSH. NO FILL. BRI F SUB, SN, TBG. OPMA @ 4650'. SN (200 BBLS. DR, PUMP, LIFT SUB, K-BARS, RDS.	, 2 3/8" TBG. TAG FILL @ 4675'. JB, X/OVER, 2 CHECK VALVES, SN, TBG. SET PKR @ 4009'. LO 661' W/12,000 GALS 15% NEFE DH W/TBG & PKR. TIH W/50 JTS BREAK CIRC W/330 BW. UNAE SH @ 4661'. CUT ON TOP OF FS EAK CIRC W/250 BBLS. MILL OI @ 4616'. PKR/TAC @ 3923'. NE HANG WELL ON. LOAD/TEST/C	HCL & 6000# RK SLT. RU SWAB. FL @ 2200'. TO 1557'. BLE TO GET CIRC. ROTAT4E THRU TIGHT SH. PULL SHOE TO 4005'	

I hereby certify that the information	n above is true and complete to the best	gake TITLE	Engineering Assistant	DATE	= 1/6/00
TYPE OR PRINT NAME	J. Denis	e Leake		Teleph i one	No. 397-0405
(This space for State Use) APPROVED	Way Jan All College	* 1			
BUNDITIONS OF APPR	OVAL IF ANY:	_TITLE		DATE	Nichols 12-93 per 1.0