

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐				
		5. State Oil & Gas Lease No. B-1306				
		7. Unit Agreement Name -				
		6. Farm or Lease Name N.M. "R" St. NCT-1				
		9. Well No. 2				
		10. Field and Pool, or Wildcat Vacuum Grayburg San Andres				
1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 2. Name of Operator TEXACO Inc. 3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 6 TOWNSHIP 18-S RANGE 35-E N.M.P.M.		12. County Lea				
15. Elevation (Show whether DF, RT, GR, etc.) 3982' (DF)						
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data <table border="0"> <tr> <td> NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐ </td> <td> PLUG AND ABANDON ☐ CHANGE PLANS ☐ </td> <td> SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER <u>Repair casing leak</u> ☒ </td> <td> ALTERING CASING ☐ PLUG AND ABANDONMENT ☐ </td> </tr> </table>			NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER <u>Repair casing leak</u> ☒	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER ☐	PLUG AND ABANDON ☐ CHANGE PLANS ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER <u>Repair casing leak</u> ☒	ALTERING CASING ☐ PLUG AND ABANDONMENT ☐			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.						

1. Rig up. Pull rod & pump. Install BOP. Pull tbg.
2. Set RBP @ 3915'. Dump 2 sx. sand on top of plug.
3. Set cement retainer @ 1894'.
4. Pump 2 Bbl. fresh water preflush. Pump 42 bbl. Howco Special Gelling Agent. Follow by squeezing leak w/200 sx Class "C" Cement w/2% CaCl. WOC.
5. Drill out cement. Test 5-1/2" csg w/600# for 30 minutes, 10:10-10:40 a.m., 1-8-77. Tested OK.
6. Pull RBP. Clean out to TD.
7. Run pumping equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. L. Chaffor TITLE Asst. Dist. Supt. DATE 1-18-77

APPROVED BY _____ TITLE _____ DATE 1-18-77

CONDITIONS OF APPROVAL, IF ANY: