

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SALESMAN	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3-NMOCC
1-R. J. STARRAK-TULSA
1-A. B. CARY-MIDLAND

1-PWS, ENGR.
1-FILE

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
E-7653

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO ABANDON OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO ABANDON OR PLUG BACK TO A DIFFERENT RESERVOIR.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER
2. Name of Operator
Getty Oil Company
3. Address of Operator
P. O. Box 730, Hobbs, NM 88240
4. Location of Well
UNIT LETTER A 330 FEET FROM THE North LINE AND 990 FEET FROM
THE East LINE, SECTION 7 TOWNSHIP 18S RANGE 35E NMPM.

7. Unit Agreement No.
8. Form or Lease Name
State "AN"
9. Well No.
1
10. Field and Pool, or Wildcat
Vacuum Abo
12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER Squeeze off water flow ☒
PLUG AND ABANDON ☐
CHANGE PLANS ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit.
2. Install BOP.
3. POH with tubing and rods.
4. Run cement bond log to determine cement top.
5. Test for gas holes.
6. Plug the gas hole and bridge plug.

ILLECIBLE

18. Signature
Area Superintendent
DATE
MAR 6 1980