

NEW MEXICO OIL CONSERVATION COMMISSION

5-NMOCC-HOBBS 1-PJB, ENGR.
1-R. J. STARRAK-TULSA 1-FILE
1-A. B. CARY-MIDLAND
1-PWS, ENGR.

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

E-7653

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN A WELL BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101, FOR OTHER PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Getty Oil Company
3. Address of Operator
P. O. Box 730, Hobbs, NM 88240
4. Location of Well
UNIT LETTER G 1650 FEET FROM THE North LINE AND 2310 FEET FROM
THE East LINE, SECTION 7 TOWNSHIP 18S RANGE 35E NMPL.

7. Unit Agreement Name

8. Farm or Lease Name

State "AN"

9. Well No.

3

10. Field and Pool, or Wildcat

Vacuum Abo, Reef

15. Elevation (Show whether DF, RT, CR, etc.)

12. County

Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

OTHER Reperforate & acidize ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOG ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit.
2. Spot acid. Perforate with 4" Jumbo jet from 8805' to 8879'.
3. Run in and set packer at 8800'.
4. Acidize lower perms.
5. Move packer up to 8475'.
6. Acidize perms.
7. Swab load and place back on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dale R. Crockett

TITLE Area Superintendent

DATE 11-19-79

Orig. Signed by

Jerry Sexton

APPROVED BY Dist 1, Supv.
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE