

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Blanco Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87305

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-03107	
5. Indicate Type of Lease STATE ☒ FEE ☐	
6. State Oil & Gas Lease No. E-7653	
7. Lease Name or Unit Agreement Name: State "AN"	
8. Well No. #7	
9. Pool name or Wildcat Vacuum ABO Reef	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐
2. Name of Operator Chevron-Texaco, Corp.
3. Address of Operator P. O. Box 3109, Midland, TX 79702
4. Well Location

Unit Letter I : 2310 feet from the South line and 990 feet from the East line

Section 7 Township 18S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐
OTHER: ☐	

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐	
OTHER: ☐	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Tag 5 1/2" CIBP @ 8650' spot 25 Sx plug 8650'-8450' (ABO) Tag @ 8405'
2. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
3. Spot 60 Sx plug 4800'-4200' (San Andres) Tag @ 4146'
4. Cut 5 1/2" Csg @ 3350' unable to pull Sqz w/75 Sx (8 5/8" shoe Yates, B-Salt) Tag @ 3300' Re-spot Cmt 3300'-2800' Tag @ 2520'
5. Perf 6 holes @ 1600' (T-Salt) Sqz Perf 1600'-1400' Sqz w/50 Sx Tag @ 1383'
6. Perf 6 holes @ 400' Circ Cmt 400' to Surf w/125 Sx (13 3/8" Shoe) Tag @ 35'
7. Circ Cmt 35' to Surf w/10 Sx, Install dry hole marker. 10/24/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Poly Aralos TITLE MANAGER

DATE 10/24/01

Type or print name POLY ARALOS

Telephone No. 683-4996

APPROVED BY [Signature] TITLE Field Rep

DATE 1-29-02

Conditions of approval, if any:

GWW