

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-03107
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E 7653
7. Lease Name or Unit Agreement Name	
State "AN"	
8. Well No.	7
9. Pool name or Wildcat	Vacuum Abo Reef
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3961' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Texaco Exploration and Production Inc.
3. Address of Operator
P.O. Box 730 Hobbs, New Mexico 88240

4. Well Location
Unit Letter I : 2310 Feet From The South Line and 990 Feet From The East Line
Section 7 Township 18S Range 35E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Test Casing for TA</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-13-91
1. Conducted casing integrity test on the above well.
 2. Tested 5 1/2" casing from CIBP @ 8650' to surface w/300# for 30 minutes. Held OK.
 3. Request temporarily abandon well status through 11-21-96.

(COPY OF CHART ON REVERSE SIDE)

ORIGINAL CHART TAKEN TO MR. RAY SMITH OF THE NMOC

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Engineer's Assistant DATE 11-21-91


TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)


APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 11-21-96



State AN #7



BR-2221
B 0-1000-8

TEXAS
INSTRUMENT ENGINEERS
(I) 7-18-35

Texaco Inc
State AIA #7
11-13-91

PRINTED IN U.S.A.

State AN #7