

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

(Form C-102)  
(Revised 7/1/52)

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG <b>WIKX Zone</b>	<b>XX</b>	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE	<b>XX</b>	NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Hobbs, New Mexico  
(Place)

July 20, 1964  
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

**Skelly Oil Company** Hobbs, **NM** Well No. **1** in **"D"**  
(Company or Operator) Lease (Unit)  
**NW**  $\frac{1}{4}$  **NW**  $\frac{1}{4}$  of Sec. **8**, T. **18-S**, R. **31-E**, NMPM., **Vacuum Drinkard** Pool  
(40-acre Subdivision)  
**Lea** County.

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

This well is a dual completion oil well in the Drinkard and Abo Zones. The Drinkard Zone of this well was Temporarily Abandoned on March 1, 1963. We plan to Plug and Abandon the Drinkard Zone of this well in the following manner:

1. Move in and rig up pulling unit.
2. Pull 2-1/16" OD tubing and set expendable plug in Model "D" Packer at 8810'.
3. Squeeze Drinkard perforations 8450 - 8476' with 100 sacks of regular cement.
4. Drill out cement, mill on and retrieve Model "D" Packer from 8810'.
5. Run rods and tubing and put well on pump from Abo Zone 8824 - 8874'.
6. Return well to production status.

Approved....., 19.....  
Except as follows:

Approved  
OIL CONSERVATION COMMISSION

By.....  
Title.....

**Skelly Oil Company**  
Company or Operator

By.....  
(ORIGINAL) **H. E. Aab**

Position.....  
Dist. Supt.  
Send Communications regarding well to:

Name.....  
Address.....  
**Skelly Oil Company**  
**Box 730 - Hobbs, New Mexico**