

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6940	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Reeves ADO State
3. Address of Operator 105 South 4th St., Artesia, NM 88210		9. Well No. 2
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM <u>East</u> LINE, SECTION <u>14</u> TOWNSHIP <u>18S</u> RANGE <u>35E</u> NMPM.		10. Field and Pool, or Wildcat Reeves Penn
15. Elevation (Show whether DF, RT, GR, etc.) 3893' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well as follows:

RIH w/tubing to 7031'. Spot 25 sx plug. Lay down 5300' tubing. Tagged cement at 6700'. Could not release casing patch. Cut casing at 4980' and pulled.

Spot 40 sx plug at 5051'. Tagged plug at 4864'.

Spot 30 sx plug at 3322-3206'.

Spot 30 sx plug at 1508-1382'

Spot 10 sx surface plug.

Cut off head and weld on abandonment marker.

Plugging completed 1-2-87.

Verbal approval for plugging given by Mr. Jerry Sexton, NMOC, Hobbs, NM, on 12-29-86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lyle F. Turnaclyff TITLE Production Supervisor DATE 1-5-87

APPROVED BY Lyle F. Turnaclyff TITLE OIL & GAS INSPECTOR DATE DEC 23 1988

CONDITIONS OF APPROVAL, IF ANY: