

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Bishop Canyon Uranium Corporation Hobbs, New Mexico
(Address)

LEASE Hookin Hill WELL NO. 1 UNIT D S 17 T 18 R 35

DATE WORK PERFORMED May 16, 1957 POOL Wildcat

This is a Report of: (Check appropriate block) Results of Test of Casing Shut-off
 Beginning Drilling Operations Remedial Work
 Plugging Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Ran 321' of 8 5/8" X 24# casing. Cemented w/ 300 sacks. Circulated, set 24 hrs. Tested w/1000 cold water for 30 minutes. No drop in pressure.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

OIL CONSERVATION COMMISSION

Name _____
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.
Name Robert S. Shivers
Position _____
Company Bishop Canyon Uranium Corp.