

CONDITION OF HOLE & PROCEDURE

Page 2

Reeves "A" Well No. 4-26

April 9, 1984

12. Swab test.
13. If nonproductive, proceed as follows.
14. RIH w/tbg & CIBP. Set @ 8970'. Spot 35' cmt on CIBP.
15. Pull up to 8840' & spot 250 gal NE acid. POOH w/tbg.
16. Perf Bone Spring w/csg gun 2 SPF @ 8822-33' (24 shots).
17. RIH w/~~strd~~ ^{pk} ~~assy.~~, Set RBP @ 8875' & pkr @ 8772'.
18. Acid w/1500 gal 15% NE, FE, LST. Swab test.
19. Return to production ASAP.

MIDLAND DISTRICT ENGINEERING

G. O. Papp:dr

RECEIVED

APR 26 1984

U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
HOLDS OFFICE