

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

DEC 12 10 02 AM '66

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-3496

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator AZTEC OIL & GAS COMPANY	8. Farm or Lease Name State AJ
3. Address of Operator P. O. Box 837, Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER K , 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 18-E RANGE 36-E NMPM. Ark. Junct. - San Andres (EXT)	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3807 K. B.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Recomplete in San Andres <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work began 11/21/66 and was finished on 11/29/66:

1. Squeezed Queen perforations at #452-66 with 100 sxs. Incor neat.
2. Ran 4 3/4" bit, and drilled out cement and bridge plugs to 5211'.
3. Perforated three - 3/8" holes at 5157, 5163, and 5186.
4. Acidized perms at 5157, 5163, and 5186 with 1000 gallons 15% N.E. acid.
5. Installed pumping equipment and after recovering load pumped 43 Bbls oil and 107 Bbls. water.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

original signed by:

LESTER L DUKE

SIGNED _____ TITLE **District Superintendent**

DATE **December 9, 1966**

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____