		Form C -103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
		5a. Indicate Type of Lease
U.S.G.S.		State X Fee
OPERATOR		5. State Oil & Gas Lease No. B-2317
SLINDRY	NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPI USE "APPLICATIO	NOTICES AND REPORTS ON WELLS OSALS TO SPILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. IN FOR PERMIT - "FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL X GAS WELL X	01469.	
2. Name of Operator		8, Farm or Lease Name
V. H. Westbrook 3. Address of Crember		State of New Mexico 9. Well No.
P.O. Box 2264, Hobbs,	New Mexico 88240	1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER B	990 FEET FROM THE NORTH LINE AND 1650 FEET	Undesignated
THE East LINE, SECTION	N 29 TOWNSHIP 18-S HANGE 36-E	NMPM.
	18. Plevation (Show whether DF, RT, GR, etc.)	12, County
	3836 G. L.	Lea
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB OTHER Re-Entry	ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB OTHER Re-Entry	PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	COMMENCE ORILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
17. Describe / roposed or Completed Operators) SEE RULE 1103. 1. Drilled out 10 sk processed and the second of th	change plans commence orilling opns. Casing test and cement JqB other Re-Entry ecutions (Clearly state all pertinent details, and give pertinent dates, incomplug at surface; 29 sk at 4749	PLUG AND ABANDONMENT [
other 17. Describe Troposed or Completes Crework) SEE RULE 1103. 1. Drilled out 10 sk producted Hole to 3. Hung 5½" Liner in 9.4. Cemented liner w/24 Pipe 5. Pressured up 9 5/8% 6. Perforated 5499 to 7. Re perforated same 8. Frac w/20,000 gals	commence orilling opns. Casing Test and cement Job Other Re-Entry Decitions (Clearly state all pertinent details, and give pertinent dates, inc. plug at surface; 29 sk at 4749 5650' 9 5/8" Casing - Top liner 4670' Bottom 5632' 40 sks polymix, 50 sks neat w/2% CaCl. Reve " & 5½" Liner to 500#s. Held. 5509. Acidized w/500 gals, 15% Acid Swabbed zone - Treated w/1000 gals, 7½% Acid - Swal & 15,000 # Sand. Waiting to test well.	PLUG AND ABANDONMENT Pluding estimated date of starting any proposition Pluding estimated date of starting any proposition and propo

DOT 30 1979

Orig. Signed by

Les Clements

Oil & Gas Inspections of Approval, 15 Any: