

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-03979

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

VA-0579

7. Lease Name or Unit Agreement Name

State RA

8. Well No.

1

9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER

SWD

2. Name of Operator

Unichem International Inc.

3. Address of Operator

P.O. Box 1499, Hobbs, New Mexico 88240

4. Well Location

Unit Letter K : 1980 Feet From The South Line and 1909' Feet From The WEST Line

Section

31

Township

1SS

Range

36E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, CR, etc.)

3834' est

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-23-92 Rigged up DAS PU and drill out surface plug. TTH w/ WS and
tagged solid plug @ 4547'. Prep to sqz perfs @ 3670' - 3714',
and 4432' - 4458'.
3-27-92 SQZ perfs @ 4432' - 4458' SICN
3-28-92 SQZ perfs @ 3670' - 3714' SICN
3-29-92 Drill out cement and test casing to 500 PSI - OK
CHART TURNED IN to EON
3-30 to 4-14-92 Drill out SHOE plug and junk TAG solid plug @ 6400'
prep to acidize OH section 4600 - 6400'
4-15-92 Acidize OH section 4600' - 6400' w/ 5000 gal 20% HFC
4-16-92 RD PU - prep to install surface equipment

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

DATE

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

COPIED BY RAY SMITH

APR 29 '92

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: