STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we, at torics accrives	T	
DISTRIBUTION		
SANTA PE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION P. O. BOX 2088

SANTA FE. NEW MEXICO 87501

Form C-103 · Revised 10-1-78

SANTA TE, NEW MEXICO 87501	
FILE	5a. Indicate Type of Lease
U.S.G.S. LAND OFFICE	State X Fee
OPERATOR .	5. State Oil & Gas Lease No.
O'ETHION	
	mmmmmm
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" IFORM C-101) FOR SUCH PROPOSALS.)	
1.	7. Unit Agreement Name
OIL GAB OTHER-	N. HOBBS (G/SA) UNIT
2. Name of Operator	8. Form or Lease Name
SHELL OIL COMPANY	SECTION 14
3. Address of Operator	9. Well No.
P. O. BOX 991, HOUSTON, TX 77001	421
4. Location of Well	10. Field and Pool, or Wildcat
11 2210 NODEN	HOBBS (G/SA)
UNIT LETTER H	amentiitiinin
FAST : 1/ 10 C 27 F	
THE EAST LINE, SECTION 14 TOWNSHIP 18-S RANGE 37-E NMPM	AIIIIIIIIII)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3681 DF	LEA ()()()
16. Check Appropriate Box To Indicate Nature of Nation Benefit of Other	Las Dava
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	
NOTICE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	· · 一
OTHER	
OTHER	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
OTHER	estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.	estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703.	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP.	354' to 3374' to
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1	354' to 3374' to
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx Cl 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs.	354' to 3374' to
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx Cl 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs.	354' to 3374' to
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx Cl 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held squeeze	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 11-7-81: Retrieved BP @3949'.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held squeeze	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 11-7-81: Retrieved BP @3949'.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held of the same	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held of the state of the salt per sy Plus 100 sy Class "C" cmt. Woc 24 hrs. 11-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status. * PER NEW MEXICO OIL CONSERVATION COMMISSION REQUEST.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx CI 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held 1-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held of the state of the salt per sy Plus 100 sy Class "C" cmt. Woc 24 hrs. 11-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status. * PER NEW MEXICO OIL CONSERVATION COMMISSION REQUEST.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1705. 10-28-81: CO to 3975'. 10-29-81: Set RBP 03949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP 02294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer 02294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes 02385' - 2386' to 500 psi - held 11-7-81: Retrieved BP 03949'. 11-8-81: Well complete and returned to TA'd status. * PER NEW MEXICO OIL CONSERVATION COMMISSION REQUEST.	ass "C" cmt <u>plus</u> neld OK.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 10-28-81: C0 to 3975'. 10-29-81: Set RBP @3949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP @2294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer @2294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes @2385' - 2386' to 500 psi - held of the state of the salt per sy Plus 100 sy Class "C" cmt. Woc 24 hrs. 11-7-81: Retrieved BP @3949'. 11-8-81: Well complete and returned to TA'd status. * PER NEW MEXICO OIL CONSERVATION COMMISSION REQUEST.	854' to 3374' to ass "C" cmt <u>plus</u>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1705. 10-28-81: CO to 3975'. 10-29-81: Set RBP 03949'. Tested previously squeezed Bowers perfs 33 500 psi - held OK. Spotted sand on top of RBP. 10-30-81: Perf'd 2385' to 2386'. Set CIBP 02294'. Pumped 1500 sx C1 10# salt per sx Plus 100 sx Class "C" cmt. WOC 24 hrs. 11/2-5/81: Drld out cmt retainer 02294' and cmt to 2540'. 11-6-81: Pressure tested squeeze holes 02385' - 2386' to 500 psi - held 11-7-81: Retrieved BP 03949'. 11-8-81: Well complete and returned to TA'd status. * PER NEW MEXICO OIL CONSERVATION COMMISSION REQUEST.	ass "C" cmt <u>plus</u> neld OK.