

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-73

1a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	N. HOBBS (G/SA) UNIT
SHELL OIL COMPANY	8. Farm or Lease Name
3. Address of Operator	SECTION 23
P. O. BOX 991, HOUSTON, TX 77001	9. Well No.
4. Location of Well	241
UNIT LETTER <u>N</u> , <u>990</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>2310</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>23</u> TOWNSHIP <u>18-S</u> RANGE <u>37-E</u> N.M.P.M.	10. Field and Pool, or Wildcat
	HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3686' DF	LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER _____		OTHER <u>OPENED ADDITIONAL PAY AND ACIDIZED</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-01 to 8-04-83: Clean out to 4350'.  
8-05-83: Perforated 4214' to 4295' (24', 48 holes).  
8-08-83: Acidized perforations w/3500 gals 15% HCl-NEA.  
8-09-83: Installed production equipment and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Eddie Curtis A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE AUGUST 25, 1983  
ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY \_\_\_\_\_ DISTRICT 1 SUPERVISOR TITLE \_\_\_\_\_ DATE AUG 29 1983  
CONDITIONS OF APPROVAL, IF ANY: