

COPIES RECEIVED		
DISTRIBUTION		
SA. TA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-1461
7. Unit Agreement Name
8. Farm or Lease Name
State "E"
9. Well No.
1
10. Field and Pool, or Wildcat
Hobbs - G/SA
12. County
Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- ☐

2. Name of Operator
Amerada Hess Corporation

3. Address of Operator
Drawer "D", Monument, New Mexico 88265

4. Location of Well
UNIT LETTER E, 1650 FEET FROM THE North LINE AND 990 FEET FROM
THE West LINE, SECTION 24 TOWNSHIP 18-S RANGE 37-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled production equipment. Ran tubing and treating packer. Spot 500 gallons paraffin solvent to desolve paraffin and swab back lead. Acidize 5½" casing perfs from 4094' to 4115' and from 4140' to 4150' in the Grayburg/San Andres zone with 3,000 gallons 20% regular acid. Swab back load and run production equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. O. Porter TITLE Admin. Services Supvr. DATE 3/25/76

APPROVED BY Orig. Signed by Les Clements TITLE Oil & Gas DATE MAR 26 1976

CONDITIONS OF APPROVAL, IF ANY: