Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe New Mexico 87504-2088 WELL API NO. 30-025-<del>20038</del> 85478

P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lesse No.
SUNDRY NOTICES AND REPORTS ON WELLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT
1. Type of Well: Off. GAS WELL X WELL OTHER	SECTION 24
2. Name of Operator	8. Well No.
Shell Western E&P Inc.	422
3. Address of Operator Cost & Adds	9. Pool name or Wildcat
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (wck 4465)	HOBBS (G/SA)
4. Well Location  Unit Letter H : 2310 Feet From The NORTH Line and	330 Feet From The EAST Line
	NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3671' DF	<i></i>
11. Check Appropriate Box to Indicate Nature of Notice, R	eport, or Other Data
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CASING TEST AND CEMENT JOB L

OTHER:\_

OAP & ACD; SI

## 6-16 TO 6-24-93:

**PULL OR ALTER CASING** 

OTHER:

POH W/PROD EQMT. CO W/BIT & SCRPR TO 4100'. SET CIBP @ 4040'. PERF GRAYBURG 3963' - 4034' (1 SPF). ACD PERFS 3998' - 4034' W/1000 GAL 15% HCL W/AS-66. SET RBP @ 3992' & PKR @ 3955'. ATTMPTD TO PRES UP BACKSIDE. FOUND LK IN CSG AROUND WH. REL PKR & RBP, RESET RBP/PKR 15' INSIDE TOL. REPLCD PITTED CSG (7 IN. COLLAR + 4' 7 IN. CSG). ATTMPTD TO PT BACKSIDE, PKR COMM. REL PKR/RBP, POH. RUBBERS TORN ON RBP, BUT NOT ON PKR. SET RBP 15' INSIDE TOL, PKR @ 3843'. PT TOL TO 500#, BLED OFF IN 2 MIN. PT BACKSIDE, HELD. REL PKR & POH. REL RBP & RESET @ 3992'. ACD PERFS 3963-87' W/1250 GAL 15% HCL W/AS-66. COMM AROUND BACKSIDE. REL PKR & OVERFLSH BACKSIDE. REL RBP & RESET IMMED ABV CIBP @ 4040'. SET PKR @ 3945'. PT BACKSIDE TO 500#, BLED TO 0 IN 1.5 MIN BUT COULD NOT PMP INTO. TAG FL @ 3000' FROM SURF. SWB TBG DRY W/NO PROD. REL PKR & RBP. SET RBP @ 3945'. POH W/PKR. RIH W/RETRV'G HD & TBG, LEFT IMMED ABV RBP. CIRC INHIB FL. FLNG UP WELLIS SI WILL TA WELL

I hereby cartify that the information above is true and complete to the best of my knowledg	e and belief.	
SIGNATURE J. Morres Winds	TITLE TECH. MANAGER - ASSET ADMIN.	DATE 8/19/93
TYPE OR PRINT NAME J. L. MORRIS		TELEPHONE NO. 713/544-3797

(This space for State Use)

APPROVED BY-

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR \_ TITLE -

AUG 25 1993

X

CONDITIONS OF APPROVAL, IF ANY: