

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29098
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 24
2. Name of Operator Shell Western E&P Inc.	8. Well No. 422
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCK 4413)	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter H : 2310 Feet From The NORTH Line and 330 Feet From The EAST Line Section 24 Township 18S Range 37E NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3671' DF


11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: WSO, DO CIBP, REPERF & ACD <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-09 TO 10-18-91:

POH W/PROD EQMT. CO TO CIBP @ 4124'. SET CICK @ 4000'. SQZD SA PERFS 4048-78' W/
100 SX CLS C CMT + 2% CACL2. TAG CICK @ 4000'. DRLD THRU CICK & CMT TO CIBP @ 4124'.
DRLD CIBP & CMT TO 4254'. RAN GR STRIP LOG. PERF SA 4130' - 4254' (2 SPF). ACD PERFS
4130' - 4254' W/4200 GAL 15% NEFE HCL + 2500# ROCK SALT. INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE DIV. ENVIRONMENTAL ENGR. DATE 11/05/91
TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3426

(This space for State Use) ORIGINAL NOTED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: