

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 24
8. Well No. 241
9. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Shell Western E&P Inc.
3. Address of Operator P.O. Box 576 Houston, TX 77001-0576 (WCK 4587)	4. Well Location Unit Letter N : 330 Feet From The SOUTH Line and 2310 Feet From The WEST Line Section 24 Township 18S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3675' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: WSO, OAP & ACD <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-17 TO 2-25-92:

POH W/PROD EQMT. CO TO 4180'. PERF SA 4112-65' (2 SPF). SET PKR @ 4100'. LD BACKSIDE & PT TO 500#, HELD. REL PKR & RESET @ 4172'. LD BACKSIDE & PT TO 500#, HAD SLIGHT BLEED OFF. PMPD 100 BBLS PW DWN TBG, SAW NO COMM. REL PKR & POH. SET CIBP @ 4180'. ACD PERFS 4155-65' W/2100 GAL 15% NEFE HCL + 150# ROCK SALT. ATTEMPTD TO ACDZ PERFS 4112-27' W/ 504 GAL 15% NEFE HCL. COULD NOT BRK DN PERFS. SET RBP @ 4140'. SPOT 84 GAL 15% NEFE HCL. COULD NOT BRK DN PERFS. SPOT 1050 GAL 15% NEFE HCL, PRES CAME DWN VERY GRADUALLY. REL RBP & POH. INST PROD EQMT & RTP.

4-14 TO 4-17-92:

POH W/PROD EQMT. CO TO 4156' W/SCRPR. SET CIBP @ 4150'. PERF SA 4105-10' (2 SPF). ACD PERFS 4105-10' W/210 GAL 15% NEFE HCL. INST PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. F. N. Kelldorf TITLE TECH. MANAGER - ENVIR. ENG. DATE 5/20/92
TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3426

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY JERRY SEXTON TITLE SUPERVISOR DATE MAY 27 1992
CONDITIONS OF APPROVAL, IF ANY: