

## OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS OF WELLS

MAR 20 1947

HUBBS OFFICE

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<b>X</b>		

Midland, Texas

March 18, 1947

Place

Date

OIL CONSERVATION COMMISSION,  
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the  
**Humble Oil & Refining Co.** **N.M. State "A"** Well No. **3** in the  
 Company or Operator Lease

**3/2** of Sec. **25**, T. **18-S**, R. **37-E**, N. M. P. M.,  
**Hobbs** Field, **Lee** County.

The dates of this work were as follows: **March 13-18, 1947**

Notice of intention to do the work was (~~submitted~~) submitted on Form C-102 on **February 25** 1947  
 and approval of the proposed plan was (~~granted~~) obtained. (Cross out incorrect words.)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Pulled 2½" tubing, ran Gamma Ray survey, and ran tubing to bottom of hole. Circulated hole with mud and plugged back from 4220' to 4000' with 100 sacks of cement. Pulled tubing and shot 7" casing at 1600', 1300', and 1000'. Pulled 34 joints of 7" casing and cemented hole from 1000' to 800' with 90 sacks of cement. Laid down 34 joints of 9-5/8" casing and plugged well from 190' to 160' with 25 sacks of cement. Put 25 sack plug at surface and installed regulation manhole.

Witnessed by \_\_\_\_\_ Name \_\_\_\_\_ Company \_\_\_\_\_ Title \_\_\_\_\_

Subscribed and sworn before me this \_\_\_\_\_

I hereby swear or affirm that the information given above is true and correct.

**18th** day of **March**, 19 **47**

Name \_\_\_\_\_

Position **Asst. Division Superintendent****Winnie Mae Fygen**

Notary Public

Representing **Humble Oil & Refining Co.**  
Company or OperatorMy commission expires **6-1-47**Address **Box 1600 - Midland, Texas**

Remarks:

APPROVED  
 MAR 20 1947  
 Date \_\_\_\_\_

**Ray Garbary**  
 Name  
**Oil & Gas Inspector**  
 Title

1. The first part of the document is a list of the names of the persons who were present at the meeting.

2. The second part of the document is a list of the names of the persons who were absent from the meeting.

3. The third part of the document is a list of the names of the persons who were present at the meeting.

4. The fourth part of the document is a list of the names of the persons who were present at the meeting.

5. The fifth part of the document is a list of the names of the persons who were present at the meeting.

6.

7. The sixth part of the document is a list of the names of the persons who were present at the meeting.

8. The seventh part of the document is a list of the names of the persons who were present at the meeting.

9. The eighth part of the document is a list of the names of the persons who were present at the meeting.