

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND	FICE
OPE	OR

# NEW MEXICO OIL CONSERVATION COMMISSION

Form O-103  
Revised 1-1-63  
Oil and Gas Division  
New Mexico

Fee ☐

**X**

B-159

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN A WELL OR TO A DIFFERENT PURPOSE. USE APPLICATION FOR PERMIT - "A" FOR SUCH PROPOSALS.)

ALL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

New Mexico 'C'  
DD & B State

TEXACO Inc.

3. Address of Operator

P.O. Box 728 Hobbs, New Mexico 88240

1

4. Location of Well

Hobbs Grayburg  
San Andres

UNIT LETTER **A** 330 FEET FROM THE **North** LINE AND 330 FEET

THE **East** LINE, SECTION **25** TOWNSHIP **18S** RANGE **37E**

15. Elevation (Show whether DF, RT, GL, etc.)

3660 DF

Lea

16.

Check Appropriate Box To Indicate Nature of Notice or Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK  
COMMENCEMENT OF  
CASING TEST AND PLUG

OTHER **Deepen Well** ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and if work) SEE RULE 1103.

1. Pull rods, pump and tubing.
2. Drill to 4245 TD.
3. Run 400' 4 1/2" liner with liner hanger @ 3800'.
4. Cement down liner w/20 sx class 'C' cement w/.3% CFR-2 and 3# salt per sack. Check top of liner.
5. Perforate selected intervals as determined from SNP log.
6. Acidize perforations w/2000 gals 15% NEA in 4 equal stages w/150 gal gelled brine water containing 25-50 # Benzoic acid flakes and 25-100 # rock salt w/each stage. Flush w/22 bbls water.
7. Run tubing, pump and rods and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED

TITLE **Asst. Dist. Supt.**

2-13-75

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: