

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>A-3071</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>STATE GG-30</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Goodwin Drinkard</b>
12. County <b>Lea</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator <b>Continental Oil Company</b>
3. Address of Operator <b>Box 460, Hobbs, N.M. 88240</b>
4. Location of Well UNIT LETTER <b>K</b> <b>2310</b> FEET FROM THE <b>South</b> LINE AND <b>1650</b> FEET FROM THE <b>West</b> LINE, SECTION <b>30</b> TOWNSHIP <b>18-S</b> RANGE <b>37-E</b> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3739' GR.</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <b>PB-7400' + Perf + Test Drinkard</b> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

**STATE GG-30 #1 OBJECTIVE: ABANDON ABO - PERF & TEST DRINKARD**

**BEFORE**  
AFE #: NONE

TD: 7732' PBD 7512'  
PERFS: 7416'-7490'  
DF ELEV: 3755'  
CSG: 5-1/2" SET AT 7732'  
FORMATION: ABO  
TESTED: SHUT-IN 4-1-69

WORK STARTED: 6-6-77  
WORK DONE: SET CIPB AT 7400'. DUMPED 35' CMT ON TOP OF CIPB.  
SPOT 200 GALS 15% HCL-NE ACID. PERF DRINKARD 7161'-7172' W/1  
JSPF. PMPD 1000 GALS 15% HCL-NE ACID AT 1 BPM. DISPLACE W/30  
BBLs TFW. MADE SEVERAL SWAB RUNS. LAST SWAB RUN, 200 BBLs  
FLUID, 1% OIL.

**AFTER**

TD: PBD - CIPB 7400'  
PERFS: 7161'-7172'  
DF ELEV: NC  
CSG: NC  
FORMATION: DRINKARD  
TESTED: 6-10-77 SWBD 200 BBLs  
FLUID 1% OIL. SHUT-IN.

WORK COMPLETED: 6-11-77

*Expire 11/1/76 (2nd)*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. D. Butterfield TITLE ADMIN. SUPV. DATE 12-28-77

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JAN 8 1978  
NMAOCC-4 F. 10