Submit 3 Copies to Appropriate District Office District 1

District II

OTHER:

State of New Mexico Energy, minerals and Natural Resources Department

Form C-103

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Revised 1-1-89

- 05526

30 - 025

WELL API NO.

P.O.Drawer DD, Artesia, NM 88210 Sal	nta Fe, New Mexico 8/504-2088	5. Indicate Type of Lease
District III		STATE X FEE
1000RioBrazos Rd.Aztec,NM87410		6. State Oil & Gas Lease No. E-7183
SUNDRY NOTICES AND		
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR, USE		7. Lease Name or Unit agreement Name
(FORM C-101) FOR S		
1. Type of Well: OIL GAS WELL X WELL	отнея	EAST EUMONT UNIT
Name of Operator OXY USA INC.		8. Well No.
3. Address of Operator		9. Pool name or Wildcat
P.O. Box 50250 Midlar	nd, TX 79710	EUMONT YATES SVN RVR QN
4. Well Location		
_		
Unit Letter F : 2,310 Feet From	The NORTH Line and 2,310	Feet From The WEST Line
Unit Letter F : 2,310 Feet From Section 33 Township	the the and	Peet From The WEST Line NMPM LEA County
Section 33 Township	The the and	. = 4
Section 33 Township	18 S Range 37 E D. Elevation (Show whether DF, RKB, RT, GR, etc.)	NMPM LEA County
Section 33 Township	18 S Range 37 E D. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,704 Box to Indicate Nature of Notice, Repo	NMPM LEA County
Section 33 Township 10 11. Check Appropriate NOTICE OF INTENTIO	18 S Range 37 E D. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,704 Box to Indicate Nature of Notice, Repo	NMPM LEA County ort, or Other Data
Section 33 Township 10 11. Check Appropriate NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG AN	18 S Range 37 E D. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,704 Box to Indicate Nature of Notice, Repo	ort, or Other Data EQUENT REPORT OF: X ALTERING CASING
Section 33 Township 10 11. Check Appropriate NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG AN	18 S Range 37 E D. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,704 Box to Indicate Nature of Notice, Repo ON TO: ND ABANDON REMEDIAL WORK	ort, or Other Data EQUENT REPORT OF: X ALTERING CASING OPNS. PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3970'

PBTD - 3969'

PERFS - 3756' - 3936'

OTHER: RE-ACTIVATE

MIRU PU, 12/22/93, NDWH NUBOP, RIH & TAG @ 3921'. CHC, CO TO 3969'. RIH & SET CIBP @ 3945'. PERF PENROSE W/ 2 SPF @ 3756-77, 84-3794, 3801-09, 22-27, 31-37, 38-41, 45-52, 59-64, 68-3880', TOTAL 166 HOLES. ACIDIZE W/ 5000GAL 15% NEFE HCL ACID. POOH, RIH W/ 2-7/8" TBG & SET @ 3917', NDBOP, NUWH, RDPU 12/27/93. RUPU 2/23/94, RIH W/ 2-1/2"X 1-1/2"X 16' BHD PUMP ON 76 RD STR, RDPU. PUT WELL ON TEST 5/12/94.

NMOCD 24HR POTENTIAL TEST - 11/22/94 - 1-BO 1-BW 6-G 6000-GOR 37.1

I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE	Man State ITTLE	REGULATORY ANALYST	DATE 12 02 94	
TYPEORPHINI NAME	DAVID STEWART		TELEPHONE NO. 915 685-5717	
(This space for State Use)	Octobase section is the reaction		D50 4 H	
APPROVED BY	File is a wartening style time		DEC 0 7 1334	

PERENED 300 15 1034 CARGEOS