110 MODERN FIRE PROOF ROOMS REAL FOOD

"MORE THAN A HOTEL ITS A HOME"



F. C. WARD MANAGING DIRECTOR

> Mr. F. J. Vesely, Oil & Mas Inspector, Carlsbad, New Mexico.

Dear Mr. Vesely:-

We have drilled down to 4506 on the Linam No. 1 well, and have encountered nothing that would justify us in going farther, considering the difficulty of drilling at that depth with so much water in the hole. We want to plug back now and get that sulphur water shot off that was encountered at 4262, and then treat with acid from top of plug to bottom of caling, or 2878.

We are enclosing in doubleate report on deepening well, and in triplicate notice of intention to plug buck, shut off water and treat with acid.

If these papers are not in proper form, or if there is anything further you require, kindly so advise.

Very Truly Yours,

Talbott & Mullineaux By Devig 1. Lerbott

SECROLL 1