

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 30
8. Well No. 111
9. Pool name or Wildcat HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3650' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter D : 330 Feet From The NORTH Line and 330 Feet From The WEST Line Section 30 Township 18S Range 38E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3650' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: OAP & Acdz <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CD to 4256' (TD).
3. Set CIBP @ 4110'.
4. Perf San Andres 4081'-92' (2 JSPF).
5. Acdz perf 4081'-92' w/500 gals 15% NEFE HCl.
6. KO CIBP @ 4110' & push remnants to TD.
7. Install prod equip & ret well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 8-15-89
(713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SIXTON

AUG 18 1989

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: