

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

1958 MAY 10 AM 8 50

COMPANY O. D. Alsabrook, 519 First National Bank Building, Dallas, Texas
(Address)

LEASE Saunders WELL NO. 1 UNIT J S 3 T 18 S R 38 E

DATE WORK PERFORMED May 16, 1958 POOL Wilcoat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☒ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Plug - 25 sacks Cement. 4907' to 4826' - Top of San Andres.
Plug - 25 Sacks Cement. 4104' to 4022' - Top of Queen.
Plug - 25 Sacks Cement. 3232' to 3151' - Top of Yates.
Plug - 25 Sacks Cement. 323 ' to 242 ' - Bottom of Surface pipe.
Plug - 10 Sacks Cement. 32 ' to 0 ' - Top of Surface Pipe.
Plugs spotted by Halliburton - Sack Cement.
Job Satisfactorily Completed

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name John W. Runyan
Title _____
Date NOV 10 1958

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Howard P. Helmer
Position AGENT

Company O. D. ALSABROOK