

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO SEEPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Indicate Type of Well OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL WESTERN E&P INC.		8. Form or Lease Name SECTION 18
3. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		9. Well No. 241
4. Location of Well UNIT LETTER <u>N</u> <u>330</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>2310</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>18</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> N.M.P.M.		10. Field and Pool, or Window HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.) 3670' DF		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☒	COMMENCE DRILLING OPER. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>WSO, OAP & ACIDIZE</u> ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103. THIS SUNDRY NOTICE SUPERSEDES C-103 DATED 9-30-85.

1. Pull production equipment. Tag btm.
2. Clean out to TD (4325').
3. Test 4" liner top to 500 psi.
4. Set cmt retainer @ 4150'.
5. Sqz San Andres perf's 4208' - 4285' w/approx. 100 sx Class "C" cmt w/2% CaCl₂ + Halad-4. Dump 10' cmt on retainer. WOC 24 hrs.
6. Drill out retainer and cmt.
7. Pres test sqz to 500 psi.
8. Perf San Andres 4236' - 4273' and Grayburg 3979' - 4051' (2 JSPF, 48 holes).
9. Acidize perf's 4236' - 4273' w/2000 gals 15% HCl-NEA.
10. Acidize perf's 3979' - 4051' w/1600 gals 15% HCl-NEA.
11. Install production equipment and return well to production.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE DECEMBER 20, 1985

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

DEC 26 1985

APPROVED BY _____ TITLE _____ DATE _____