

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 18
3. Address of Operator P. O. BOX 991, HOUSTON, TX 77001	9. Well No. 231
4. Location of Well UNIT LETTER K 1980 FEET FROM THE SOUTH LINE AND 1901 FEET FROM THE WEST LINE, SECTION 18 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3676' DF	12. County LEA

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

OTHER OPEN ADDITIONAL PAY AND ACIDIZE; RETURN ☒  
WELL TO PRODUCTION

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Clean out to PBTD (4164'). Drill out CIBP @ 4164' and cement below. Clean out to 4289'.
- Spot 250 gals 15% HCl NEA across zone to be perforated.
- Perforate 4-1/2" casing 3970 to 76', 3990 to 94', 4156 to 58', 4160 to 62', 4184 to 86', 4194 to 96', 4218 to 22', 4236 to 38', 4242 to 46', 4250 to 52', 4260 to 62' (43', 86 holes).
- Acidize perfs w/8100 gals 15% HCl NEA.
- Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton Jr. A. J. FORE  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

TITLE SUPERVISOR REG. & PERMITTING

DATE MARCH 16, 1983

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

MAR 22 1983