Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

7. Laser Type of Lases SINDEY NOTICES AND REPORTS ON WELLS SUNDEY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION PERMIT"  1. Type of Well:  7. Lase Name or Usit Agreement Name N. HOBS: (G/SA) UNIT  8. Well No. 11. Type of Well:  8. Well No. 12. Name of Operator Sholl Western EAP Inc. 13. Address of Operator P.O. BOX 576 Houston, TX 77001-0576  14. Well Location Usit Later A: 990. Feet From The NORTH Line and 990 Feet From The EAST Line Section 18  18. Range 38E NMTM LEA Oxwity 10. Elevation (Slow whether DF, R.E., R.F., GR, etc.)  19. Pool mane or Wildcat HOBBS (G/SA)  10. Elevation (Slow whether DF, R.E., R.F., GR, etc.)  11. OTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PEPCRAMBLY ABANDON CHANGE PLANS COMMENCE DRILLING OPINS. PLUG AND ABANDONMENT  11. Describe Proposed or Completed Operations (Clearly state all partitional details, and give pertinant dates, including estimated date of storting any proposed  11. OTICE OF INTENTION TO:  12. Describe Proposed or Completed Operations (Clearly state all partitional details, and give pertinant dates, including estimated date of storting any proposed  11. DOT 11-05-92:  IT breedy overify that the information shove is two and complete to the boot of my knowledge and ballet.  12. Describe Proposed or Completed Operations (Clearly state all partitional details, and give pertinant dates, including estimated date of storting any proposed  11. DOT 11-05-92:  12. Therefore overify that the information shove is two and complete to the boot of my knowledge and ballet.  13. House overify that the information shove is two and complete to the boot of my knowledge and ballet.  14. HODDEN  15. Lace Number 10 and ADMIN.  16. PERMITT  17. Lase Number of Using ADMIN.  18. Lase Number of Using ADMIN.  19. Permitted ADMIN.  19. Permitted ADMIN.  19. Permitted ADMIN.  19. Permitted ADMIN.  19.	DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO. 30-025-07349
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PUUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PENIAT"  1. Type of Well:  ONE OF OFFICE OF THE SERVING. USE "APPLICATION FOR PENIAT"  1. Type of Well:  ONE OF OFFICE OF THE SERVING. USE "APPLICATION FOR PENIAT"  1. Type of Well:  ONE OF OFFICE OF OFFICE OF OFFICE OF OFFICE OF OFFICE OF OFFICE	DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
CONTUSE THIS FORM FOR PROPASALS TO DRILL OR TO DEEPEN OR PLUG AND DEEPEN OR PLUG AND DEFFERENT RESERVOR. USE "APPLICATION FOR PERMIT"		
Shell Western E8P Inc.  3. Addraw of Operator P.O. Box 578 Houston, TX 77001–0576  4. Well Location Ual Letter A : 990 Feet From The NORTH Lise and 990 Feet From The EAST Lise Section 13 Township 18S Range 38E NMPM LEA Cointy 3681' DF  10. Everation (Show what har DF, RKB, RT, GR, etc.) 3681' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB COTHER: FAILED MIT (P&A PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11–02 TO 11–05–92: RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRYLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRYL.	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)  I. Type of Well:  OIL WELL X  WELL OTHER	N. HOBBS (G/SA) UNIT
1. Address of Operator P.O. Box 576 Houston, TX 77001-0576  1. Well Location Ualt Letter A : 990 Feet From The NORTH Liae and 990 Feet From The EAST Liae Section 18 Township 18S Range 38E NNIPM LEA County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3681' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  OTHER: FAILED MIT (PBA PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of storting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT NITTYL'S, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL PBA WELL FOLLOWING PARTNER'S APPRVL.  1 Describe Proposed or Complete to the bost of my knowledge said belid.  SONATURE ALL MAPPEND.		8. Well No.
P.O. Box 576 Houston, TX 77001-0576  Will Lossice  Unit Latter A: 990 Feet From The NORTH Liae and 990 Feet From The EAST Like Section 18 Township 18S Range 38E NMPM LEA County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  3681' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: FAILED MIT (PBA PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, including estimated data of starting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRYLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL PBA WELL FOLLOWING PARTNER'S APPRVL.  11 Describe Proposed or Completed Describe to the best of my beowledge and belief.  12 Describe Proposed or Completed Describe to the best of my beowledge and belief.  13 TIME TECH. MANAGER - ASSET ADMIN. DATE 3/12/93	2 44	
Unit Lester A: 990 Feet From The NORTH Line and 990 Feet From The EAST Line Section 18 Township 18S Range 38E NMPM LEA County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  3881*1 °DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: FAILED MIT (P8A PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent datalis, and give pertinent datas, including estimated date of starting any proposed work) SEE RULE 1103.  11–02 TO 11–05–92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRYLS, LOC CSG LKS BTW 412' – 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P8A WELL FOLLOWING PARTINER'S APPRYL.  1 Dendy certify that the information above is true and complete to the best of my knowledge and baild.  1 HANDERO TITLE TECH. MANAGER – ASSET ADMIN. DATE 3/12/93	1 WIK 42165 1	9. Pool name or Wildcat
Section 18 Township 18S Range 38E NMPM LEA County  10. Elevation (Shorw whether DF, RKB, RT, GR, etc.)  3681' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: FAILED MIT (P&A PENDING)  OTHER: FAILED MIT (P&A PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRYLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRYL.  I hencely certify that the information above is true and complete to the best of my knowledge and belief.  BOWNATURE ALL MODDING.  TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93	4. Well Location	HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3681' DF  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CONTINUES.  OTHER: FAILED MIT (P&A PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92: RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRYLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRYL.  1 Dentity certify that the information above is true and complete to the best of my knowledge and bolist.  SMONATURE ASSET ADMIN. DATE 3/12/93	Libe	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REMEDIAL WORK	The same of the sa	
Thereby certify that the information above is true and complete to the boat of my knowledge and belief.    Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:   SUBSEQUENT REPORT OF:   SUBSEQUENT REPORT OF:   REMEDIAL WORK	*/////////////////////////////////////	
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER: FAILED MIT (P&A PENDING)   OTHER: FAILED MIT (P&A PENDING)   12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRVLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRVL.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SMANATURE	V/////////////////////////////////////	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OCHANGE PLANS CASING TEST AND CEMENT JOB OTHER: FAILED MIT (P&A PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRVLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRVL.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SBONATURE MANAGER - ASSET ADMIN. DATE 3/12/93		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: FAILED MIT (P&A PENDING)  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRVLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRVL.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SMONATURE ACCOUNTS TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93		SEQUENT REPORT OF:
PULL OR ALTER CASING  CASING TEST AND CEMENT JOB  OTHER: FAILED MIT (P&A PENDING)  THER: FAILE	TEMEDIAL WORK	ALTERING CASING
OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:OTHER:	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11–02 TO 11–05–92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRVLS, LOC CSG LKS BTW 412' – 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRVL.  I bereby certify that the information above is true and complete to the best of my knowledge and belief.  SMONATURE AMANAGER - ASSET ADMIN. DATE 3/12/93	PULL OR ALTER CASING CASING TEST AND CEMENT JOB	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  11-02 TO 11-05-92:  RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRVLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRVL.  I bereby certify that the information above is true and complete to the best of my knowledge and belief.  BIOMATURE AMANAGER - ASSET ADMIN. DATE 3/12/93	OTHER: OTHER: FAILED M	IT (P&A PENDING)
RIH W/BIT & SCRPR. TAG TOC @ 2561'. FAILED MIT, POH. RIH W/PKR. SET PKR @ DIFFERENT INTRVLS, LOC CSG LKS BTW 412' - 1791'. POH W/WS. FLG UP WH. INFORMED NMOCD'S JERRY SEXTON WILL P&A WELL FOLLOWING PARTNER'S APPRVL.  I bereby certify that the information above is true and complete to the best of my knowledge and belief.  SKONATURE	12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
I bereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE  TITLE  TECH. MANAGER - ASSET ADMIN.  DATE 3/12/93	11-02 TO 11-05-92:	
SKONATURE O Marcus Winder TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93	DIFFERENT INTRALS, LOC CSG LKS BTW 412' - 1791', POH W/WS FIGUR WHI INFORMED	
SKONATURE O Marcus Winder TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93		
SKONATURE O Marcus Winder TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93		
SKONATURE O Marcus Winder TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93		
SKONATURE O Marcus Winder TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93		
SKONATURE O Marcus Winder TITLE TECH. MANAGER - ASSET ADMIN. DATE 3/12/93	I hereby certify that the information above is true and complete to the best of my knowledge and belief	
The second of th	OM $I$ $I$	ASSET ADMIN. DATE 3/12/93

TITLE -

(This space for State Week! SINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPPRIVISOR

MAR 19 1933

CONDITIONS OF AFFROVAL, IF ANY:

APPROVED BY-