

Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 19
8. Well No. 221
9. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)	4. Well Location Unit Letter F : 2310 Feet From The NORTH Line and 2310 Feet From The WEST Line Section 19 Township 18S Range 38E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3664' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: Set CIBP, OAP & Acdz ☒	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. Set pkr abv top of CIBP (4076') & pres tst to 1500#.
3. Pull pkr to 4030' & set. Pres tst csg to 500#.
4. Attmp to pmp into perfs @ 4052'.
 - a. If perfs do not communicate w/perfs @ 4060'-62', proceed w/remaining steps.
 - b. If communication is noted, POH to abv all SA perfs. Estab inj rt, sqz exst perfs & reperf higher in Zn.
5. Rel pkr & FOH.
6. KO CIBP @ 4076' & push to btm.
7. Set CIBP @ 4056'.
8. Perf SA 4044'-51' (2 JSPF).
9. Acdz perfs w/700 gals 15% NEFE HCl.
10. Install prod equip & ret well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. SMITHERMAN TITLE REGULATORY SUPV. DATE 1-16-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY J. H. SMITHERMAN
APPROVED BY DISTRICT SUPERVISOR TITLE
CONDITIONS OF APPROVAL, IF ANY:

JAN 19 1990