NO, OF COPIES RECEIVED	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
FILE	3-NHOCC	5a. Indicate Type of Lease
LAND OFFICE	1-Pile	State Fee
OPERATOR		5. State Oil & Gas Lease No.
LOO NOT USE THIS FORM FOR PRO	Y NOTICES AND REPORTS ON WELLS Posals to drill or to deepen or plus back to a different reservoif. Ion for permit - " (form C-101) for such Proposals.)	
1. OIL GAS WELL WELL	OTHER-	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
GETTY OIL COMPANY		BOONE HARDIN
3. Address of Operator		9. Well No.
P.O. BOX 249, HOBBS,	NEW MEXTCO 88240	1
4. Location of Well		10. Field and Pool, or Wildcat
	2310 FEET FROM THE NORTH LINE AND 2310 FEET F	HOBBS GRAYBURG
	CN 19 TOWNSHIP 188 RANGE 388 NN	
	15, Elevation (Show whether DF, RT, GR, etc.) 3662 GR	12. County LEA
	Appropriate Box To Indicate Nature of Notice, Report or NTENTION TO: SUBSEQU	Other Data ENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JO3	PLUG AND ABANDONMENT
OTHER		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Halliburton spotted 20 sacks of 20-40 sand through tubing from 4252' back to 4152'. Dumped two sacks Calseal with dump bailer. No fill. Dumped two sacks Calseal from 4152' back to 4127'. Set HOWCO cement retainer at 3703'. Tested casing with 500# and tubing with 3200#. Squeesed with 100 sacks Class "C" with 3# salt per sack and .5% CFR-2 and 100 sacks Class "C" with 3# salt per sack and 3# sand per sack and .5% CFR-2. Squeezed with 120 sacks cement in formation @ 2000#. Could not reverse out. Pulled up 400' and reversed out. Tagged cament with bit 0 3430'. Drilled solid cament to 3480'. DRilled cament stringers to 3590'. Washed to 3690'. Drilled solid cement to 3703' (retainer). Drilled retainer and solid cement to 3807', top of liner. Pulled 6-1/8" bit and ran 4-3/4" bit. Drilled cement to 4122'. After drilling into 5-1/2" liner to 3920', tested top of liner with 1000# for 30 minutes, OK. Tested perforations 3953-4110' in 5-1/2" liner with 1000# for 30 minutes, OK. Drilled Calseal from 4130-50'. Washed out sand to TD @ 4260'. Perforated 5-1/2" liner @ 4180', 81, 82, 83, 84, 85, 86, 87, 88, 93, 94, 95, 96, 97, 98, 99, and 4200' with one jet each. Ran HOWCO bridge plug and treating packer. Set BP 0 4208' and RTTS 0 4201'. Tested BP with 1700# for 25 minutes, OK. Treated perforations with 1,000 gals. 15% NE and Fe-stab acid using 24 ball scalers. Set 2-3/8" tubing @ 4236', ran rods and pump. Placed back on production.

18. I hereby certify that the information above is true and c ORIGINAL SIGNED S. : Ge Lo Wade	TITLE AREA SUPERINTENDENT	DATE September 7, 1971
APPROVED BY	TITLE SIL	SEP 1 0 1971

RELIVED

SET 0 1971 OIL CONSERVATION COMM. HOBBS, L. M.