

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-07362
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 19
8. Well No. 231
9. Pool name or Wildcat HOBBS (G/SA)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER
2. Name of Operator SHELL WESTERN E&P INC.
3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)
4. Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>19</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3663' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: CMT SQZ, OAP & ACDZ ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip.
2. CO to 4245' (PBSD).
3. Set CIBP @ 4125'.
4. Set pkr @ 4095' & pres tst CIBP + sqzd SA perfs 4102'-20' to 700#.
5. Rel pkr & reset @ 4030'. Pres tst tbg/csg ann to 500#.
6. Est inj rt into SA perfs 4084'-91'. Rel pkr & POH.
7. Set CIBP @ 4030'.
8. Sqz perfs 4084'-91' w/20 sx Cls "C" cmt + 0.75% CF-14. Cap CIBP w/10' cmt. WOC 24 hrs.
9. DO CIBP & cmt to 4100'. Pres tst sqz to 500#.
10. Cont drlg cmt & DO CIBP @ 4125'. Push CIBP to PBSD.
11. Perf SA 4062'-76' (2 JSPF).

(CONTINUED ON REVERSE SIDE)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 2-26-90
TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)

Eddie W. Searcy
Oil & Gas Inspector

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 02 1990

12. Acdz perfs 4062'-76' w/1000 gals 15% NEFE HCl.
13. Install prod equip & ret well to prod.

RECEIVED

MAR - 1 1999

CCC
HOBBS OFFICE