Submit 3 Copies

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 30-025-07371 Santa Fe. New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease FEE X STATE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" N. HOBBS (G/SA) UNIT (FORM C-101) FOR SUCH PROPOSALS.) SECTION 20 1. Type of Well: OAS WELL OIL WELL OTHER 2. Name of Operator 8. Well No. Shell Western E&P Inc. 3. Address of Operator 9. Pool name or Wildcat (WCK 4413) P.O. Box 576 Houston, TX 77001-0576 HOBBS (G/SA) 4. Well Location Unit Letter _ O 330 Feet From The 2310 Feet From The SOUTH EAST Line and 185 Township Range 38E **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3643' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK REMEDIAL WORK PLUG AND ABANDON ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMEN **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB X OTHER: OAP & AT OTHER:_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 1. POH W/PROD EQMT. 2. CO TO PBTD @ 4246' 3. RUN GR/CNL/CCL FROM PBTD TO 2748'. 4. PERF SA @ DPTS TO BE DETERMINED BY LOG EVAL. 5. AT SA W/TREATMENT SCH & VOL BASED ON LOG EVAL. 6. INST PROD EQMT & RTP.

SIGNATURE	ent of	TITLE W. F. N. KELLDORF	DATE 11/14/91
TYPE OR PRINT NAME W. F. N. KELLDORF			TELEPHONE NO. 713/870-3426
(This space for State Use)	Orig. Signed b y		
	Paul Kautz Geologist		