

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator SHELL OIL COMPANY		
Address of Operator P. O. BOX 991, HOUSTON, TX 77001		
Location of Well UNIT LETTER <u>0</u> <u>330</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>2310</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>20</u> TOWNSHIP <u>18-S</u> RANGE <u>38-E</u> NMPM.		

7. Unit Agreement Name N. HOBBS (G/SA) UNIT
8. Farm or Lease Name SECTION 20
9. Well No. 341
10. Field and Pool, or Wildcat HOBBS (G/SA)
12. County LEA

15. Elevation (Show whether DF, RT, GR, etc.)
3643' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- CO to 3886' (top of liner). Perforate 7" csg @2795 ±.
- Set RBP @2850' and spot 10' sand on top. Pump 750 ± sx cement and circulate to surface. Reverse out excess. WOC 24 hours.
- DO cement. Pressure test squeeze to 500 psi. Reverse out sand. Retrieve BP.
- Run production equipment.

* Per New Mexico Oil Conservation Commission request.

NOTIFICATION IS REQUIRED TO BE FILED IN THE OIL CONSERVATION DIVISION
24 HOURS PRIOR TO COMMENCING WORK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. J. Fore A. J. FORE TITLE SUPERVISOR REG./PERMITTING DATE JULY 31, 1981

APPROVED BY Don E. [Signature] TITLE Don E. [Signature] DATE Don E. [Signature]

CONDITIONS OF APPROVAL, IF ANY: