

It is necessary that this form be submitted by the operator befor flaturation that this form be submitted by the operator befor flaturation that the submitted of the submitted by the operator befor flaturation that the complete of the submitted of the submitted of the submitted by the operator before the submitted of the submitted of the submitted in triplicate of the submitted in triplicate to the office to which form C-101 was sent. Two copies will be retained there and the other submitted to the Proration Office, Hobbs. New Mexico. The allowable will be assigned effective 7:00 a.m. on date of completion, provided completion report is filed during month of completion. The completion date shall be that date in the case of an oil well when oil is delivered into the stock tanks. Gas must be reported on 15.025 P.B. at  $60^{\circ}$  Fahrenheit.

Hobbs, New Mexico	July 14, 1952
Place	Date

WE ARE HEREBY REQUESTING AN ALLOWABLE FOR A WELL KNOWN AS:

	C. H. Sweet	Grimes	Well No.	l-A in U	nit 1,	
	Company or Op	erator Lease				
costio	. 20 <sub>T</sub> 14	<b>385</b> , R. <b>385</b> , N.M.P.M	Hobbs	Pool	Lea	County
Please	indicate locat		Spudded 💆	((	ompleted	
		Total Depth	<b>52</b> p.	B		
			4207			
		Top ()il/Gas Pav Initial Production	To	n hater Pa 20 BDPD	ау	BOPD OR CULET
		Based on <b>20</b> Bbl	s. Oil in	lirs	·	Yins.
		Method of Test (Pi	tot, gauge,	prover. me	<pre>&gt;ter run):</pre>	
		Tubing (Size)				
		Pressures: Tubing	·	Casi!	12 <b>24 </b>	
		Gas (0il Ratio		Grav	ity <b>31.0</b>	
			Casing Per	Torations		
1.4.4.4	letter: I	4207 - 42	15			
CHLC.	1etter. <u>.</u>	- Acid Record:		Show of	f Oil.Gas a	nd water
C-ci.	& Cementing Re	and 500 Gals 4225	to <b>4235</b>	$\mathbf{S}_{i}$		
		500 <sub>Gals</sub> 4231	to <b>4236</b>			
Siz	e Feet Sa	Gals				
0 = /						
8 5/6	9 <b>° 305</b> 15	Qts	to			
<b>E1/1</b>	4959 900	Sex Qts	to	⊃		
5%	<b>42</b> 52 <b>300</b>	gnalite Qts	to	<u> </u>		· · ·
	1 6 10 <b>36X</b> . 31					
		Natural Production				
		Test after acid on	r shot: 20 B	OPD Pump	ing	Flowing
U10950	indicate below	Formation Tops(in confe				
		neastern New Mexico			stern New N	
T. Anh	1615	T. Devonian		T. Ojo Al	amo	
T. Sal	<b>2470</b>	T. Silurian		T. Kirtla	nd-Fruitla	1d
B. Sal	25683	T. Montoya			gton	
T. Yat		T. Simpson			ed Cliffs_	
T. 7 H	livers	T. McKee			House	
T. Que	en				e Lookout	
T. Gra	ayburg	T. Gr. Wash				
1. 540	Andres	T. Granite				
• • • • • •	orieta				on	
	inkard	I•		-		
T. Tut		<b>-</b> · · · · · · · · · · · · · · · · · · ·		-		
T. Per				Т.		

Τ.

\_\_\_\_\_

T. Miss \_\_

Τ.

Pipe line taking oil or g	as: Bumble Pipe Line Company
Kemarks:	
,	
	C. H. Swet
	Company or Operator
	BV: ATTINE
	Bv (#Signature
	Position: Operator
Send communications regar	ding well to:
	Name: C. H. Sweet
	Address: Box 1115, Hobbs, New Mexic
ΔΡΡΒΟΫΕΙ	, 19
	ERVATION COMMISSION
	· · · · · · · · · · · · · · · · · · ·
By:	

.