

MAPE		
le		
S.C.S.		
ND OFFICE		
ERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Order and C-1003
Effective 1-1-85

5a. Indicate Type of Lease
State ☐ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

WELL ☐ GAS WELL ☐ OTHER ☐
Name of Operator
Shell Oil Company
Address of Operator
P.O. Box 991 Houston, TX 77001
Location of Well
UNIT LETTER K 1350 FEET FROM THE south LINE AND 1350 FEET FROM
THE west LINE, SECTION 21 TOWNSHIP 18S RANGE 38E N.M.P.M.

7. Unit Agreement Name
8. Farm or Lease Name
North Grimes
9. Well No.
4
10. Field and Pool, or Wellcat
Hobbs(G/SA)
12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3645' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REPAIR REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
WILL OR ALTER CASING ☐ AMENDED	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
OTHER RE-ENTER AND REPLUG ☐			

Describe the Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Dig out cellar. Remove marker. Rig up PU and reverse circulator.
2. Drill out surface cement plug in 13" csg. CO to 1291'. Spot Class "C" cmt plug @1291' if no plug is found @1291'.
3. Spot Class "C" cmt plug from 400'-200'. Spot 10 ft Class "C" cmt plug at surface.
4. Weld plate over 13" csg. Install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY A.J. Fore TITLE Supervisor, Regulatory & Permits DATE January 30, 1981

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: