STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

MB. 07 COPIES RECEIVED	1	
MOITUBIRTEIQ		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
	1	

OIL CONSERVATION DIVISION P. O. BOX 2088

Form C-103 - Revised 10-1-78

	•
V.S.G.S.	5a. Indicate Type of Lease
LAND OFFICE	State Fee XX
OPERATOR	5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
OIL X GAS WELL OTHER-	N. HOBBS (G/SA) UNIT
Name of Operator	8. Farm or Lease Name
SHELL OIL COMPANY	SECTION 27
address of Operator	9. Well No.
P. O. BOX 991, HOUSTON, TEXAS 77001	131
ocation of Well	10. Field and Pool, or Wildcat
UNIT LETTER L	· L. HOBBS (G/SA)
THE WEST LINE, SECTION 27 TOWNSHIP 18-S RANGE 38-E NMPM	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3638' GR	I LEA C'ALLILLA
Check Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
	<u></u>
RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON COMMENCE DRILLING OPNS	PLUG AND ABANDONMENT
Summer States Transport and St	
OTHER	
OTHER OPEN ADDITIONAL PAY AND ACIDIZE - [XX]	
OTHER OPEN ADDITIONAL PAY AND ACIDIZE XX Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
OTHER OPEN ADDITIONAL PAY AND ACIDIZE . [XX] Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any proposed
OTHER OPEN ADDITIONAL PAY AND ACIDIZE XX Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE XX Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE XX Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes).	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE XX Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903. 1. Drill out to 4252' +.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bbls 15% HCl-NEA.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1603. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes).	estimated date of starting any proposed
OTHER OPEN ADDITIONAL PAY AND ACIDIZE [XX] Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bbls 15% HCl-NEA.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bb1s 15% HC1-NEA.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE [XX] Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bb1s 15% HC1-NEA.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bb1s 15% HC1-NEA.	estimated date of starting any proposed
OPEN ADDITIONAL PAY AND ACIDIZE Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bb1s 15% HC1-NEA.	estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bb1s 15% HC1-NEA. 4. Install production equipment and return well to production.	estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bb1s 15% HC1-NEA. 4. Install production equipment and return well to production.	estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bbls 15% HCl-NEA. 4. Install production equipment and return well to production.	estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bbls 15% HCl-NEA. 4. Install production equipment and return well to production.	estimated date of starting any proposed
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903. 1. Drill out to 4252' +. 2. Perforate 4054' to 73' and 4034' to 38' (25', 50 holes). 3. Acidize OH and perfs w/160 bbls 15% HCl-NEA. 4. Install production equipment and return well to production.	estimated date of starting any proposed

A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE OCTOBER 20, 1982

OCT 2 o 1982

JERRY SEXTON CONDITIONS OF APPROVAL, IF ANY

ORIGINAL SIGNED BY