

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name
N. HOBBS (G/SA) UNIT

8. Farm or Lease Name
SECTION 28

9. Well No.
421

10. Field and Pool, or Widened
HOBBS (G/SA)

UNIT LETTER H 2310 FEET FROM THE NORTH LINE AND 1120 FEET FROM
THE EAST LINE, SECTION 28 TOWNSHIP 18S RANGE 38E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
3648' GR

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER PB & ACDZ ☒

OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POH w/prod equip. Tag btm.
2. CO to at least 4240'.
3. PB w/hydromite to 4240'.
4. Acdz Grayburg/San Andres OH 4020' - 4240' w/4000 gals 15% HCl-NEA + 1800# rock salt.
5. Install prod equip & return well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

DATE 5-18-88 TITLE SUPERVISOR REG. & PERMITTING A. J. FORE

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

TITLE

DATE

MAY 23 1988

RECEIVED
MAY 20 1988
OCD
HOBBS OFFICE