

|            |  |  |
|------------|--|--|
| DATE       |  |  |
| FILE       |  |  |
| S.C.S.     |  |  |
| AND OFFICE |  |  |
| PERATOR    |  |  |

# NEW MEXICO OIL CONSERVATION COMMISSION

Effective 1-1-65

|                                |   |
|--------------------------------|---|
| 3a. Indicate Type of Lease     |   |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |   |

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

|   |   |
|---|---|
| OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   | 7. Unit Agreement Name<br>N. Hobbs (G/SA) Unit        |
| Name of Operator<br>Shell Oil Company   | 8. Farm or Lease Name<br>N. Hobbs (G/SA) Unit Sec. 28 |
| Address of Operator<br>P.O. Box 991 Houston, TX 77001   | 9. Well No.<br>231                                    |
| Location of Well<br>UNIT LETTER <u>K</u> <u>1325</u> FEET FROM THE <u>south</u> LINE AND <u>1325</u> FEET FROM THE <u>west</u> LINE, SECTION <u>28</u> TOWNSHIP <u>18S</u> RANGE <u>38E</u> NMPM. | 10. Field and Pool, or Wildcat<br>Hobbs (GB/SA)       |
| 15. Elevation (Show whether DF, RT, GR, etc.)<br>3651' GR   | 12. County<br>Lea                                     |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|   |  |   |
|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/><br>TEMPORARILY ABANDON <input type="checkbox"/><br>PULL OR ALTER CASING <input type="checkbox"/><br>OTHER <u>Deepen &amp; convert to injection</u> <input checked="" type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/><br>CHANGE PLANS <input type="checkbox"/><br>REMEDIAL WORK <input type="checkbox"/><br>COMMENCE DRILLING OPNS. <input type="checkbox"/><br>CASING TEST AND CEMENT JOBS <input type="checkbox"/><br>OTHER <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/><br>PLUG AND ABANDONMENT <input type="checkbox"/><br>OTHER <input type="checkbox"/> |
|---|--|---|

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull production equipment.
2. Set RBP @ 4130'  $\pm$ ; test; csg to 500 psi; run CBL/CCL log.
3. Deepen to a maximum of 4265' & run GR/N log from TD 4265' to 2265'.
4. Perforate interval 4089' - 4150' in San Andres Zones II & III.
5. Set prk @ 4070'; acid treat perforations w/3000 gals 15% HCL NEA.
6. Run 2 7/8" Duo-line HT 8 round J55 tbg; set pkr @ 4075'  $\pm$ .
7. Install surface equipment and return well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED A.J. Fore A.J. Fore TITLE Senior Engineering Technician

APPROVED BY [Signature] TITLE [Signature] DATE 7/18/80

CONDITIONS OF APPROVAL, IF ANY: