

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form O-102
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT WITH" (FORM O-101) FOR SUCH PROPOSALS.)

1. OIL ☒ GAS ☐ OTHER ☐
2. Name of Operator
SHELL WESTERN E&P INC.
3. Address of Operator
P. O. BOX 991, HOUSTON, TEXAS 77001
4. Location of Well
UNIT LETTER F, 2310 FEET FROM THE N LINE AND 1650 FEET FROM
THE WEST LINE, SECTION 29 TOWNSHIP 18-S RANGE 38-E WMPD.
15. Elevation (Show whether DF, RT, GR, etc.)
3653' DF
12. County
LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER WSO ☒
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPER. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull production equipment.
2. Set a CIBP @ ±3850' for water shutoff.
3. Shut well in approx. one month (or until obtaining working interest owner approval).
4. Install production equipment and return well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE MAY 8, 1985
APPROVED BY _____ TITLE _____ DATE _____