

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-07445
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 29
2. Name of Operator Shell Western E&P, Inc.	8. Well No. 341
3. Address of Operator P.O. Box 576, Houston, TX 77001 ATTN: S.A. GALIK-5239 WCK	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter <u>0</u> : <u>330</u> Feet From The <u>SOUTH</u> Line and <u>2318</u> Feet From The <u>EAST</u> Line Section <u>29</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3643' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: REPAIR LEAK @ SURFACE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/1/95 To 8/7/95

POOH w/Prod Equip. RIH w/RBP and set @ 140'. PT to 500 PSI, Wellhead leaked. NU Bell Nipple and standardized wellhead. RIH w/RBP and PKR. Set RBP @ 3850'. PT csg to 500 PSI - held good. Rel PKR and RBP.
Return well to Production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Shirley A. Galik TITLE MGR - ASSET ADMIN. DATE 10/24/95
TYPE OR PRINT NAME For: G. S. Nady TELEPHONE NO. 713/544-4219

(This space for State Use)

APPROVED BY ORIGINAL SIGNATURE TITLE SECTION DATE 10/24/95
CONDITIONS OF APPROVAL, IF ANY: